4.9 Fire Safety Risk Assessment

Risk area: Stowey Bears Preschool **Carried out by:** Rachel Penny **Date:**

Fire hazards:	Who is at risk:	Level of risk:	Control measure:	Review:
Electrical Plugs/wires/sockets	Children, staff, parents, visitors.	Low	Plugs are PAT tested yearly and any wires are not accessible to children. Wires are checked to ensure they are safe and not frayed.	Tested annually
Electrical items	As above	Low	All electrical items are PAT tested yearly in line with the Government Guidance Fire Safety Risk Assessment –Educational Premises (HMG 2006)	Tested annually.
Heaters	As above	Low	All heaters are covered to ensure they do not get too hot. Heaters are pre-set to not overheat. No items are put on top of heaters.	Fire Marshall responsible for ensuring staff adhere to the control measure
Gas boilers	As above	Low	The gas boiler is situated in the boiler room away from the preschool. The boiler is checked by Skanska (Outside agency) on a regular basis.	

Flammable materials	As above	Low	Any flammable material such as paper and craft materials are kept away from heating sources ie the wall heaters. No flammable liquids are kept within the preschool room. Cleaning liquids are kept in the kitchen away from any heat source (in under counter cupboard) or in cleaning cupboard outside of preschool room.	Fire Marshall responsible for ensuring staff adhere to the control measure
Mean of escape	As above	Low	Evacuation procedures are known to staff and are carried out on a regular basis to ensure all staff and children are aware	Carried out half termly